SIEMENS



Training manual

Sinumerik 808D Programming and Operating Procedures for Milling Version 2013-01




				1.1.1	1.1												1.1	_	



Basic knowledge of programming for milling is required, before operating of a machine !







Index

Absolute incremental dimensioning	32
Editing part program	31
Executing M function	20
Calculator	85
Changing time	74
Contour editor	46
Creating and measuring tools	13
Creating zero offsets	24
Cycles	40
Dry run	58
Jogging spindle	20
Tool wear	63
List of programming functions	109
Manual face milling	72
Manual start spindle	23

Manual tool change	15
MDA	77
Moving axis with handwheel	16
Part programming	29
Protection levels	7
Program execution	57
Block search	65
Reference point	10
RS232c and USB	69
Saving data	74
Simulation	53
Subprograms	78
Sample program	87
Timers/counters	61
ISO mode	97






Content


Unit Description

This unit describes the 808D PPU and MCP functionality, the coordinate system of a milling machine and how to enter passwords to access the system.

Unit Content



Basic Theory





MCP Moving axis

Preparation





±n•

2

Axis remove

91, °X

+ n =

The 808D machine control panel (MCP) is used to control manual operation of the axis.


The machine can be moved with the appropriate keys.

MCP OEM keys

> The 808D machine control panel (MCP) is used to control OEM machine functions. The machine functions can be activated with the appropriate keys.



0 🖗 🔳



8.808.8 8.809.8

User

interface

808D (PPU) has eight vertical softkeys (abbr. SKs) on the right of the screen. These SKs can be activated with the corresponding button (located on the right).

🚇 🚥 👿 层

T.

808D (PPU) has eight horizontal SKs on the bottom of the screen. These SKs can be activated with the corresponding button (located below).





Passwords at the control are used to set the user's right to access the system. Tasks such as "Basic Operating", "Advanced Operating" and commissioning functions all depend on the passwords.

No password Customer's password Manufacturer's password Machine operator Advanced operator OEM engineer

Set

Change

Delete

password

password



Customer's password = CUSTOMER Manufacturer's password = SUNRISE


Step 1

Usually the machine operator does not need to change the password.

The service mode is opened with the appropriate key combination. In the service mode, the password can be activated and deactivated.

Step 2

End



system

+X

Preparation


Machine coordinate

The Sinumerik 808D uses a coordinate system which is derived from the DIN 66217 standard.

The system is an international standard and ensures compatibility between machines and coordinate programming. The primary function of the coordinate system is to ensure that the tool length and tool radius are calculated correctly in the respective axis.



																		_	_	






Content

Unit Description

This module describes how to switch the machine on and reference it.

Unit Content



SEQUENCE



Please note the explicit switching on rules as specified by the machine manufacturer.

Step 1

Turn on the main switch of the machine.



The main switch is usually at the rear of the machine.

Step 2

Make sure you perform the following operation!



Release all the EMERGENCY STOP buttons on the machine!

End



SIEMENS

SEQUENCE





Step 1

Xo

Y

Ζ

0

Step 2



After power on, the machine will be in the reference point approach mode (default).

Res	set g	KP DRY ROV M01 PRT SBL	
MCS	\wedge	Reference point	
Х	•	0.000	mn
Y	Ð	0.000	nn
7	a	0.000	m

Step 3

After completing the referencing procedure for all axes, the referenced symbol is displayed next to the axis identifier.



If the axis is not referenced, the nonreferenced symbol (circle) is displayed between the axis identifier and the value.



Position

0.000

0 000

0.000

Repos offset

0.000 mm

0.000 mm

0.000 nn

30g

M

Reset

MCS

Х


Y

Ζ

After returning to JOG mode, use the axis traversing keys to move the machine manually.

The machine can now be operated in JOG mode.

During normal operation (JOG), the referenced symbol is not shown on the screen



0.000

0.000

0.000

m

mm

The axes are referenced with the corresponding axis traversing keys.

The traversing direction and keys are specified by the machine manufacturer.







																		_	_	







Content

Unit Description

This unit describes how to create and set up tools.

Unit Content







Tool Setup


SEQUENCE


Step 2

The range of tool numbers which can be created by this system is 1~32000. The machine can be loaded with a maximum of 64 tools / 128 tool edges.

New Press the "New tool" SK on the PPU tool Milling tool Drilling Select the type of tool required. tool Enter "1" at "Tool No " Tapping tool Tool list Ball end mil.tool New milling tool Tool No.: 1 Identifier milling tool ок 🗸 Press the "OK" SK on the PPU.

Enter the "Radius" of the milling tool.










Step 2

A new tool edge can be added in this way and different lengths and radii can be entered as required.

The red circle shows the actual active tool and tool edge, the purple circle shows how many tool edges have been created and the related data for each tool edge.






A maximum of nine tool edges can be created for each tool!

Different tool lengths and radii can be saved in different tool edges as required.

Please select the right tool edge for machining according to requirement!







The tool are usually loaded manually into the spindle.

The tool will be automatically loaded into the spindle with an automatic tool changer.

Move machine with handwheel



A handwheel can control the axis motion instead of the "JOG" button.


Press the "Machine" key on the PPU

Press the "Handwheel" key on the MCP



Select the axis you want to move with the appropriate keys. on the MCP





1	WCS	Position	Repos offset	U
l	®Χ	0.000	0.000 mm	w
	Y	0.000	0.000 mm	sł
	Ζ	0.000	0.000 mm	C

Inder "WCS" or "MCS" state, a handwheel vill be shown beside the axis symbols, howing the axis is chosen, and can be ontrolled with a handwheel.

Select the required override increment according to the buttons on the right (this selection fits all axes)		→ I → I 1 10 100
The override increment is "0.001 mm"		→ 1
The override increment is "0.010 mm"		→ I 10
The override increment is "0.100 mm"	$ \longrightarrow $	→ 100

The selected axis can now be moved with the handwheel.

Press "JOG" on MCP to end the function of "Handwheel".


Notes: If set the MD14512[16]=80, the system will deactivate the function of MCP for selecting the axis of handwheel, the user will have to activate "Handwheel" function with PPU softkey.

						-	Handwheel
				:	12:41:22 2012/07/03		
			SIEM	ENS	NCS		
Reset SKP DRY ROV MO1 PRT SBL WCS Position	Repos offset	T,F,S				Select the r	equired
«X 0.000	0.000 mm	T 1	D) 1	×	axis on the	right of
Y 0.000	0.000 mm	F		leex	Y	the PPU; th	e se-
Z 0.000	0.000 mm	S1		.00%	z	lected axis	is
			0.0 0			shown with	a√
691 6599(9)	660	Handwhe	nel W	CS			
		Axis	Number 1 2				
		×					
		Y	_				
		6					
					"		
				<u>-</u>	Back		
T,S,M Z REL Meas.	Meas. tool			Face cutt.	Sett.		 /




Tool Setup


SEQUENCE





Start the spindle before adjusting tools as follows:











Press the axis keys on the MCP to move the tool to the set position above the workpiece.






Note: The following text describes the required settings in the workpiece coordinate system

"X / Y / Z" zero points as: "X0" / "Y0" / "Z0"


Press the "Handwheel" key on the MPC and position the tool at location Z0 or a of the workpiece.



or



Move directly to zero point



HAND

Use a setting block.

Use "SELECT" key to set the reference point as "workpiece" (In real measurement, the reference point can be set as either "workpiece" or " fixed point" if required.

Enter "0" for "Z0" (If the setting block is used, then the value would be thickness a)





The measured tool length is now shown in "Length (L)". This value is also saved in the length value column of the corresponding tool list at the same time.

Step2 Measure diameter


Press the "Diameter" SK on the PPU








Press the axis keys on the MCP to move the tool to the set position.




Press the "Handwheel" key on the MCP and position the tool at the location X0 or a of the workpiece.



or




Move directly to zero point



Use a setting block.

Enter "0" at "X0" Enter "0" at "Y0" (This is the value of the width of a setting block if it is used. Select one of X0/Y0 according to requirement.)





Press the "Set diameter" SK on the PPU



Press the "Back" SK on the PPU





Back



SIEMENS

SEQUENCE









																		_	_	






Content


Unit Description

This unit describes how to set the workpiece offset and test the tool results.

Unit Content





SEQUENCE


















Method1

1 This method is normally for setting the zero point of the workpiece at the edge of the workpiece.


Using a tool that has a measured "Tool length & radius", move the tool to a known position on the workpiece. Using either JOG or Handwheel, scratch an edge and then calculate the zero point of the workpiece. The process of setting the "X" zero point ("X0") is described below.


Press the corresponding SK of the first icon on the right-hand side of the PPU.



Press the appropriate SK to select the feed axis which needs to be set up.

Press the axis traverse keys to move the tool to the required setting position in the X axis.





"Step 2" must be repeated for the setting of Y and Z zero points. If you change the tool because of wear/damage during the machining process, you must remeasure the length of the tool.



Workpiece Setup

SEQUENCE

Method 2 This method is normally used for setting the workpiece zero point at the center point of a rectangular workpiece.

Using tools with a measured "length and radius", move them to the four edges of the rectangular workpiece. Using either JOG or Handwheel, scratch an edge and then calculate the zero point of the workpiece.

Press the corresponding SK of the second icon on the right-hand side of the PPU.

Observing the figure on the PPU, move the coordinate axis following the orange arrow to move the tool to the specified position and scratch the edge of the workpiece.

Press the "Save P1" SK on the PPU to save the coordinate axis of the 1st position in the system.

Repeat the process for positions 2, 3 and 4. (When the setting is complete, the buttons will be shown in blue.)

Press the "Set WO" SK on the PPU.

Workpiece neasurement,	center of rectangle				v
zt 📲	Work offset	654 U		Save P4	Y
	Offset	× ₈ 33.499	m	Set WO	th
X I		Y ₀ 136.380		«	ce
Compensation data ha	we been activated!			Back	re
👢 T,S,H 🍠 Set 🗾	Meas. Neas. work. tool		Face cutt.	Sett.	

You have then finished setting the zero point of the workpiece as the center point of the rectangular workpiece.

Save P1

Save P1

iave P2

ave P3

Save P4

Set WN Method 3 This method is normally used for setting the zero points at the center point of a circular workpiece.

Using tools with a measured "length and radius", move them to the three edges of the circular workpiece. Using either JOG or Handwheel, scratch an edge and then calculate the zero point of the workpiece.

Press the corresponding SK of the third icon on the right-hand side of the PPU.



Observing the figure on the PPU, move the coordinate axis following the orange arrow to move the tool to the specified position and scratch the edge of the workpiece.

Press the "Save P1" SK on the PPU to save the coordinate axis of the 1st position in the system.



Repeat the process for positions 2 and 3. (When the setting is complete, the buttons will be shown in blue.)



Set

ыn

Press the "Set WO" SK on the PPU.



You have then finished setting the zero point of the workpiece as the center point of the circular workpiece.



Workpiece Setup

SEQUENCE



The tool setup and workpiece setup must have been performed correctly so that it can be tested as follows!

In order to ensure the machine safety and correctness, the results of the tool offset should be tested appropriately.

Press the "Machine" key on the PPU.	MACHINE
Press the "MDA" key on the MCP.	MDA
Press the "Delete file" SK on the PPU.	Delete file
Enter the test program recommend- ed on the right. (can also be cus- tomized)	G54 (select offset panel as required) T1 D1 G00 X0 Y0 Z5
Press the "ROV" key to ensure that the "ROV" function is activated (the function is activated when the light on the key is on).	

Note: The ROV function activates the feedrate override switch under the G00 function.



Make sure the feedrate override on the MCP is at 0%!

Press "CYCLE START" on the MCP.



Increase the feedrate override gradually to avoid accidents caused by an axis moving too fast. Observe whether the axis moves to the set position.








Content

Unit Description

This unit describes how to create a part program, edit the part program and get to know the most important CNC commands required to produce a workpiece.

Unit Content



Basic Theory



Header T, F, S function Geometry data / motion Return to change tool T. F. S function Geometry data / motion Return to change tool T, F, S function Geometry data / motion Return to change tool End/stop motion

A standard program structure is not needed but is recommended in order to provide clarity for the machine operator. Siemens recommends the following structure:

N5 G17 G90 G54 G71

N10 T1 D1 M6 N15 S5000 M3 G94 F300 N20 G00 X100 Y100 Z5 N25 G01 Z-5 N30 Z5 N35 G00 Z500 D0

N40 T2 D1 M6 N45 S3000 M3 G94 F100 N50 G00 X50 Y50 Z5 N55 G01 Z-5 N60 Z5 N65 G00 Z500 D0


N70 T3 D1 M6 N75 S3000 M3 G94 F100 N80 G00 X50 Y50 Z5 N85 G01 Z-5 N90 Z5 N95 G00 Z500 D0


N100 G00 G40 G53 X0 Y0 Z500 D0 M30




Create Part Program Part 1

SEQUENCE







The system will save it automatically after editing.









Basic Theory



The program shown in the editor can be created and edited with the appropriate keys.

G	N	^E O	Ρ	* 7	8	9
×	۷Y	Ψz	°c	^{\$} 4	*5	6
1	^A J	ĸ	R	1	[®] 2	"3
M	Ŝ	۲ ⁽	, r	-	0	1
F	D	н	В	•/	=	²+
6 SHIFT	CTRL	ALT	-	₩	DEL	INSERT.
	_				TAB	HARDT
ALARMA GANCEL	MANSONA MANSONA		Plate			
MENU FUNCTION		SELECT		MACHINE	PRCERAM	OFFSET
(1) HELP	END	▼	PAGE NO	PROGRAM	SYSTEM ALAYM	CUSTOM





N5 G17 G90 G54 G71

N10 T1 D1 M6 N15 S5000 M3 G94 F300 N20 G00 X100 Y100 Z5 N25 G01 Z-5 N30 Z5 N35 G00 Z500 D0


G70

With G70 at the header, the geometry data will be in the imperial (inches) unit system, the feedrate in the default metric system.

Header
T, F, S function
Geometry data / motion
Return to change tool

N5 G17 G90 G54 G70


N10 T1 D1 M6 N15 S5000 M3 G94 F300 N20 G00 X3.93 Y3.93 Z5 N25 G01 Z-0.787 N30 Z0.196 N35 G00 Z19.68 D0





SIEMENS

Basic Theory



G90

Absolute positioning; with G90 at the header, the geometry data which follows will be interpreted relative to the active zero point in the program, usually with G54 or G500 or G500 + G54.

N5 G17 G90 G54 G71

N10 T1 D1 M6 N15 S5000 M3 G94 F300 N20 G00 X100 Y100 Z5 N25 G01 Z-20 N30 Z5 N35 G00 Z500 D0

G91

Relative positioning; with G91 you can add an incremental value (G91-defined data is the relative positioning using the present position as the start point). Finally you should change the program to absolute positioning with G90.


N5 G17 G90 G54 G70

N10 T1 D1 M6 N15 S5000 M3 G94 F300 N20 G00 X3.93 Y3.93 Z0.196 N25 G01 G91 Z-0.787 N30 Z0.196 N35 G00 G90 Z19.68 D0





Basic Theory



N5 G17 G90 G54 G71

N10 T1 D1 M6 N15 S5000 M3 G94 F300 N20 G00 X50 Y50 Z5 N25 G01 Z-5 N35 G00 Z500 D0

N5 G17 G90 G54 G71

N10 T1 D1 M6

N15 S5000 M3 G94 F300 N20 G00 X50 Y50 Z5 N25 G01 Z-20 N35 G00 Z500 D0

- Feedrate .
- Spindle speed .
- Feed type .
- **Spindle direction**

In the program, the feed rate is defined with "F". Two types of feed rate are available.

1. Feed per minute \rightarrow G94

2. Feed per revolution of the spin-

dle →G95

G94

Defines the feed rate in terms of time (unit: mm/min).

G95

Defines the feed rate in terms of spindle revolutions (unit: mm/rev). S

The spindle speed is defined with "S"

S5000

M3/M4

The spindle direction is defined with M3 and M4. clockwise and counter-clockwise respectively. G01


When G01 is activated in the program, the axis will traverse at the programmed feed rate in a straight line, according to the feed rate type defined by G94 or G95.

N5 G17 G90 G54 G71

N10 T1 D1 M6 N15 S5000 M3 G94 F300 N20 G00 X50 Y50 Z5 N25 G01 Z-5 N30 Z5 N35 G00 Z500 D0

N5 G17 G90 G54 G71





changer.

with automatic tool



SIEMENS

Basic Theory



Activation/ deactivation of the tool radius compensation when working on the part contour.


G41 / G42 and G40

With G41/G42. the tool radius compensation will be done in the direction of travel

G41: Compensation to left

G42: Compensation to right

G40: Compensation of the radius can be deactivated



 $G42 \rightarrow direction$ along the tool motion, tool is always on the right of the contour

> Arrow indicates the direction of tool motion along the contour.

When traversing circular contours with cutter radius compensation, it should be decided whether the feed rate should be calculated along the contour of the workpiece or along the path defined by the center point of the cutting tool.

When using a contour with a feed rate defined by the CFC code, the feed rate will be constant at the contour. but in some cases, it may cause increases in the feed rate of the tool

This increase could damage the tool if excessive material is encountered at the contour; this function is normal for finish cutting of contours

The **CFTCP** command ensures a constant feed rate. however a constant feed rate may not be ensured at the contour, which may cause deviations in surface finish

Contour feedrate with CFC

 \cap Direction for compensation. left of contour will be G41

Feedrate calculated when using tool center, inside or outside of the contour

The result of the two commands will be such that the cutter goes very fast around a corner or slow on the contour







Basic Theory

Milling circles and

arcs The circle radius shown in the example on the right can be produced with the specified part program code. When milling circles and arcs, you must define the circle center point and the distance between the start point / end point and the center point on the relative coordinate When working in the XY coordinate system, the interpolation parameters I and J are available.

N5 G17 G90 G500 G71

N10 T1 D1 M6 N15 S5000 M3 G94 F300 N20 G00 X-20 Y-20 Z5 N25 G01 Z-5 N30 G41 X0 Y0 N35 Y50 N40 X100 N45 G02 X125 Y15 I-12 J-35 N50 G01 Y0 N55 X0 N60 G40 X-20 Y-20 N35 G00 Z500 D0


Note: N45 can also be written as follows N45 G02 X125 Y15 CR=37

Two common types of defining circles and arcs:

①:G02/G03 X_Y_I_J_; ②:G02/G03 X_Y_CR=_;

Arcs \leq 180°, CR is a positive number Arcs >180°, CR is negative number





- SP = start point of circle
- CP = center point of circle
- EP = end point of circle

I = defined relative increment from start point to center point in X

J = defined relative increment from start point to center point in Y


G2 = define circle direction in traversing direction = G2 clockwise

G3 = define circle direction in traversing direction = G3 counterclockwise













																		_	_	






Content

Unit Description

This unit describes how to create a part program, edit the part program and get to know the most important CNC commands required to produce a workpiece.

Part 2

Unit Content



Basic Theory



The two radii and the chamfer shown in the diagram can be produced with the code marked in the program below.

RND = Radii

line)

CHR = Chamfer

CHF=Chamfer


base line)

actual effect

(specified side length of isosceles

triangle with chamfer as base

(specified base line length of




N55 SUPA G00 Z300 D0 N60 SUPA G00 X300 Y300 N65 T3 D1 N70 MSG("Please change to Tool No 3") N75 M05 M09 M00

N80 S5000 M3 G94 F300 N85 G00 X-6 Y92 N90 G00 Z2 isosceles triangle with chamfer as N95 G01 F300 Z-10 N100 G41 Y 90 N102 G01 X 5 N105 G01 X12 RND=5 N110 G01 Y97 CHR=2 N115 G01 X70 RND=4 N120 G01 Y90

N125 G01 G40 X80 N130 G00 Z50








With the "OK" SK, the values and cycle call will be transferred to the part program as shown below.

This will drill a hole at the current position.

With the Modal call SK, holes will be centered at subsequent programmed positions until cancelled with the MCALL command in the part program. The information is transferred as shown below.




RTP
RFP
SDI
DP
DPR
DTB
N325 MCA 2.000, -5.0 N330 X20 N335 X40 N340 MCA N345 X60 centered

Parameters	Meanings
RTP=50	Coordinate value of turning position is 50 (absolute)
RFP=-3	Coordinate value of hole edge starting position under workpiece zero point surface is 3 (absolute)
SDID=2 (frequently used values 2~5)	Safety distance, feed path changes from quick feed to machine feed 2 mm away from RFP face
DP=-5	Coordinate position of final drilling depth is -5 (absolute)
DTB=0.2	Delay of 0.2 s at final drilling depth

Operating and Programming — Milling








Drill

drilling.

The relevant cycle can now be found using the vertical SKs on the right.

Deep hole drilling


Select "Deep hole drilling" using the vertical SKs and parameterize the cycle according to requirements.



With the "OK" SK the values and cycle call will be transferred to the part program as shown below. This will drill a hole at the current position.


With the "Modal call" SK, holes will be drilled at subsequently programmed positions until cancelled with the MCALL command in the part program.

The information is transferred as shown below



For specific parameter commands, see the next page

N325 MCALL CYCLE83(50.00000, -3.00000, 1.00000, .9.24000, .5.00000, 90.00000, 0.70000, 0.50000, 1.00000, 0, 0, 5.00000, 1.40000, 0.60000, 1.60000) N330 X20 Y20 ; Hole will be drilled N335 X40 Y40 ; Hole will be drilled N340 MCALL N345 X60 Y60 : Hole will not be drilled



~

n۲





For descri	ptions of RTP, RFP, SDIS and DP, ple	ase see page 40
FDEP=5	Reach first drilling hole depth. Z axis coordinate is -5 (absolute coordinate value)	
FDPR=5	From the reference plane, drill down- wards 5mm	
DAM=90	Decrement is 90	
DTB=0.7	Pause 0.7 s during final tapping of thread depth (discontinuous cutting)	DTB <0: Unit is r
DTS=0.5	Stops at the start position for 0.5 s (for VARI=1, removal active)	DTS <0: Unit is r
FRF=1 (range:0.001~1)	Original effective feed rate remains unchanged	Feed rate modulus
VARI=0	Interruption in drilling is active	VARI=1 retraction of active quill back to reference plane
AXN=3	AXN is tool axis, under appointed G17 use Z axis	The value of AXN decides which axis to use
MDEP=5	Minimal drilling depth 5 mm	This parameter activates only when DAM <0
VRT=1.4	Interruption in drilling, the retraction value of the quill is 1.4 mm	VRT=0 → retraction value is 1mm VRT>0 → retraction value is appoint- ed value
DTD=0.6	Pauses at the position of final drilling depth for 0.6 s	DTD <0:unit is r, DTD =0:same as DTB
DIS1=1.6	When reinserting a quill, you can program a distance limit of 1.6 mm	For specific explanations please refer to the standard handbook

DAM parameter


①DAM≠0, the first drilling operation (FDPR) cannot exceed the drilling depth. As of the second drilling operation, the drilling is acquired from the last depth operation (drilling depth=last drilling depth-DAM). The calculated drilling must be >DAM. If the calculated drilling is ≤DAM, as of the next feed, the DAM value will be the feed depth until the end of the feed. If the last remaining depth is <DAM, then drilling is performed automatically until the required depth is reached.

②DAM=0, drilling depth each time is same as the 1st drilling depth (FDPR), In case the residual depth <2xFDPR, the last 2 cutting depth are half of the residual depth.

Example:	40 mm deep hole as	an example, w	ith DAM=2 ı	mm and DAM=0 mm	feed
Feed times	Every feed depth/ mm DAM=2	Actual depth/ mm	Feed times	Every feed depth/ mm DAM=0	Actual depth/ mm
1.	FDPR=10	-10	1.	FDPR=10	-10
2.	FDPR-DAM=10-2=8	-18	2.	FDPR=10	-20
3.	(FDPR-DAM)-DAM =8-2=6	-24	3.	FDPR=10	-30
4.	(FDPR-2DAM)- DAM =6-2=4	-28		maining depth =10 < 2 naining depth distribute ling	
5.	(FDPR-3DAM)- DAM =4-2=2	-30	4.	5	-35
6.	DAM=2	-32	5.	5	-40
7.	DAM=2	-34	6.		
8.	DAM=2	-36	7.		
9.	DAM=2	-38	8.		
10.	DAM=2	-40	9.		\rightarrow








📕 Drill

The relevant cycle can now be found using the vertical SKs on the right.



Select "Thread" using the vertical SKs ,and then select "Rigid tapping", and parameterize the cycle according to requirement.



With the "OK" SK, the values and cycle call will be transferred to the part program as shown below. This will drill a hole at the current position.

If there is no other operation, the machine will drill holes in the current position.

With the "Modal call" SK, holes will be tapped at subsequently programmed positions until cancelled with the MCALL command in the part program.


Examples are shown on the next page .



Page 43








N325 MCALL CYCLE84(50.00000, -3.00000, 2.00000, ,6.00000, 0.70000, 5, ,2.00000, 5.00000, 5.00000, 5.00000, 3, 0, 0, 0, 5.00000, 1.40000) N330 X20 Y20 ; Hole will be tapped N335 X40 Y40 ; Hole will be tapped N340 MCALL

N345 X60 Y60 ; Hole will not be tapped



For descriptions of RTP, R	RFP, SDIS, DP and DTB, please see p	age 40
For descriptions of AXH, V	ARI, DAM and VRT, please see page 4	12
Parameters	Meanings	Remarks
DTB=0.7	Pause 0.7 s during final tapping to thread depth (discontinuous cutting)	
SDAC=5	Spindle state after cycle is M5	Enter values 3/4→M3/M4
PIT=2 (Range of val- ues:0.001~2000 mm)	Right hand thread with 2mm pitch	Evaluate value→left hand thread
POSS=5	Spindle stops at 5° (unit: °)	
SST=5	Tapping thread spindle speed is 5 r/min	
SST1=5	Retraction spindle speed is 5 r/ min	Direction is opposite to SST SST1=0 →speed is same as SST




SST and SST1 control the spindle speed and the Z axis feed position synchronously. During execution of CYCLE 84, the switches of the feed rate override and the cycle stop (feed hold) are deactivated.

Operating and Programming — Milling








🥂 Drill

	N:\MPF\DEMO_PART_1.MPF	103
The relevant cycle	HOLES2	Center point of hole circle, 1st axis
can now be found		CPA 36.00000
using the vertical	Y 🛔	CP0 24.10000
0		RAD 10.00000 STA1 90.00000
SKs on the right.		STA1 90.00000 INDA 60.00000
	O C STAI	NUM 6
Hole Hole	CPO	
pattern → circle		
Select		
"Hole pattern" using		
the vertical	CPA ×	
SKs ,and then se-		
lect "Hole circle",		Cancel
and parameterize		
the cycle according		пк 🗸
, ,		UK
to requirement.		
808D		F

With the "OK" SK, the values and cycle call will be transferred to the part program as shown below. This will drill holes at the positions defined from within the cycle.



N325 MCALL CYCLE82(50.00000, -3.00000, 2.00000, -5.00000, 0.00000, 0.20000)

N330 HOLES2(36.00000, 24.10000, 10.00000, 90.00000, 60.00000, 6) N335 X36 Y24.1 N340 MCALL : Modal Call OFF

Parameters	Meanings
CPA=36	Center of hole circle horizontal coordinate is 36 (absolute value)
CPO=24.1	Center of hole circle horizontal coordinate is 24.1 (absolute value)
RAD=10	Circle radius is 10 mm
STA1=90	Angle between the circle and horizontal coordinate is 90°
INDA=60	Angle between the circles is 60°
NUM=6	Drill 6 holes on circle
The cy	cle is used together with the drilling fixed cycle to decrease the hole clearance

Operating and Programming — Milling



SIEMENS

Basic Theory

Contour milling with cvcle

The easiest way to rough and finish around a contour is to use the contour milling function. The cycle can be

found and parameterized via the "Mill " SK

	13:05:59 2012/04/2
N:\MPF\DENO_PART_1.MPF 58	Face
;=====================================	milling
N430 SUPA G00 Z300 D0 1	
N440 SUPA G00 X300 Y300 1	Contour
;==================Conturmilling start ¶	nilling
N450 T2 D1 1	
N460 MSG("Please change to Tool No 2") ¶	Standard
N470 M05 M09 M00 1	pockets
N480 S5000 N3 T	
1490 CYCLE72("CONT1:CONT1_E", 50.00000, 0.00000, 2.000000, -5.000000,	
5.00000, 0.00000, 0.00000, 300.00000, 100.00000, 111, 41, 12, 3.000	Spigot
80, 300.00000, 12, 3.00000) 1	
;========================Conturmilling end ¶	Slots
N500 SUPA G00 Z300 D0 ¶	Slots
N510 SUPA G00 X300 Y300 ¶	
;======================Rectangular pocketmilling start ¶	Thread
N520 T2 D1 1	nilling
N530 MSG("Please change to Tool No 2") ¶	
N540 M05 M09 M00 T	HighSpee
N550 56500 N3 T	settings
N560 POCKET3(50.00000, 0.00000, 1.00000, -3.00000, 40.00000, 30.000	
00, 6.00000, 36.00000, 24.10000, 15.00000, 3.00000, 0.10000, 0.10000	
📝 Edit 🛃 Cont. 🛃 Drill. 📕 Hill. 💽 Active 纙 Simu	. 💽 Re-

Mill

The "Contour milling" SK can be found in the vertical SKs on the right.

Contour milling

The parameterization is performed as in this figure.

EVELE72		Name of contour sub-	outine	
CVILE72	_KNAME _RTP _SDIS _DP _MID _FAL _FALD _FFP1 _FFD _VARI	Name of contour sub CONT1 CONT1 E 50,00000 0,00000 2,00000 5,00000 5,00000 0,00000 0,00000 300,00000 100,00000		New file Attach contour
×	_vnk1 _RL _AS1 _LP1 _FF3 _AS2 _LP2	111 41 12 3.00000 300.00000 12 3.00000	0	Cancel



The contour can be edited and stored in the main program file after the M30 command when using the "Attach contour" SK.

	13:85:59
3%	2012/04/25
N:\MPF\DEH0_PART_1.HPF 58	Face
;=====================================	milling
N430 SUPA G00 Z300 D0 1	
N440 SUPA G00 X300 Y300 1	Contour
;=================Conturnilling start f	
N450 T2 D1 1 N460 NSG("Please change to Tool No 2") 1	Constant
N460 NSG("Please change to lool No 2") 1 N478 N85 M89 N88 ¶	Standard pockets
N488 S5888 M3 1	pockets
490 CYCLE72("CONT1:CONT1 E", 50.00000, 0.00000, 2.00000, -5.00000,	
5,00000, 0,00000, 0,00000, 300,00000, 100,00000, 111, 41, 12, 3,000	Spigot
88, 388,00000, 12, 3,00000) ¶	
;================Uonturwilling end 1	
N500 SUPA G00 Z300 D0 1	Slots
N510 SUPA G00 X300 Y300 1	
;=====================================	Thread
NS20 T2 D1 1	nilling
NS30 NSG("Please change to Tool No 2") ¶ NS40 N05 M09 N00 ¶	
NSSA SESAA NA 1	HighSpeed
HSS0 56500 HS 1 NS60 POCKET3(50.00000, 0.00000, 1.00000, -3.00000, 40.00000, 30.000	settings
HS60 POLKEIS(50.00000, 0.00000, 1.00000, -3.00000, 40.00000, 30.000 99, 6.00000, 36.00000, 24.10000, 15.000000, 3.00000, 0.10000, 0.10000	
88, 8,86666, 38,86666, 24,16666, 13,86666, 3,86666, 8,16666, 8,16666	
🗃 Edit 🛃 Cont. 🚽 Drill. 🚽 Mill. 💽 Active 🚙 Simu	
	Comp.

Enter the cycle data setting according to the former operations in the screen and enter the name of the contour subprogram.

Press the "Attach contour" SK on the PPU. This will create a "contour information segment" at the end of the program, and the cursor will move to the writing position Attach automatically. contour

N:\MPF\DEMO_PART_1.NPF mmslotnilling start N410 S7000 M3 1 N420 SLOT2(50.00000, 0.00000, 2.00000, -5.00000, 2.00000, 3, 30.000 00, 6.00000, 38.00000, 70.00000, 20.00000, 165.00000, 90.00000, 300 00000, 300.00000, 3.00000, 3, 0.20000, 2000, 5.00000, 250.00000, 800 0.00000.) 1 Search ====Slotnilling end 1 N430 SUPA 600 Z300 D0 1 N448 SUPA 688 X388 Y388 1 Hark On ===Conturnilling start ¶ N450 T2 D1 1 N460 MSG("Please change to Tool No 2") 1 Сору N470 M05 N09 M00 1 N480 S5000 M3 1 CYCLE72 ("CONT1". , , , , , ,11, 41, 1, , ,1,)¶ Paste UNT1 E::*******CONTOUR ENDS*********** 🗐 Edit 🛛 🛃 Cont. Tech interface

Make sure that the cursor has moved to the contour writing position (as shown in the figure).


Press the "Cont." SK on the PPU to open the screen for setting the contour 📕 Cont. data.

CONT1:1






When you have opened the screen for setting the contour data, you can make the following settings:




Enter appropriate start point coordinates as in the machining figure and select the correct approach.

Press the "Accept element" SK on the PPU.



Use the arrows on the PPU to select the direction and the shape of the contour milling.


Enter the corresponding coordinate parameters.



The selected direction is shown at the top left side of PPU.

The meanings of the highlighted positions is shown at the bottom of the PPU screen.

Press the "Accept element" SK on the PPU.



Select different items (SKs) to set the contour until finishing editing the whole shape of the contour.

Press "accept" SK on PPU to input the contour information in the main program



actual effect

New

300.00000, 12, 3.00000)

Basic Theory

Create Part

Program Part 2

After completing the steps, the system will return to the edit interface. Press "Technical interface" on the PPU to return to the interface for setting the cycle data.

Tech interface


After finishing the parameter settings of CYCLE72, press the "OK" SK on the PPU to insert the corresponding cycles in the main program.



With the "New" SK and "Contour milling", the operation can be edited and saved in a subprogram.

The editing in the subprogram is the same as above.

With the "OK" SK, the values and the cycle call are transferred to the part program as shown below.



N245 CYCLE72("CONT1:CONT1_E", 50.00000, 0.00000, 2.00000, -5.00000, 5.00000, 0.00000, 0.00000, 300.00000, 100.00000, 111, 41, 12, 3.00000,


Parameters	Meanings	Remarks
KNAME= CONT1:CONT1_E	Set the name of the contour subprogram as "CONT1" (":CONT1_E" is automatically created)	The first two positions of the program name must be letters
MID=5	The maximal feed depth is 5 mm	
FAL=0	Finishing allowance at the contour side is 0 mm	
FALD=0	Finishing allowance at the bottom plane is 0 mm	
FFP1=300	Tool feed rate on plane is 300 mm/min	
FFD=100	Feed rate after inserting the tool in the material is 100 mm/min	
VARI=111	Use G1 to perform rough machining, and back to the depth defined by the RTP+SDIS at the completion of the contour	For other parameters, please refer to the standard manual
RL=41 (absolute value)	PL=41→use G41 to make tool compensa- tion on the left side of the contour	PL=40→G40, PL=42→G42
AS1=12	Approach the contour along the 1/4 circle on the path in space	For other parameters, please refer to the standard manual
LP1=3	The radius of the approaching circle is 20 mm	The length of the approaching path is along the line to ap- proach
FF3=300	The feed rate during retraction of the path is 300 mm/min	
AS2=12	Return along the 1/4 circle on the path in space	Parameter explanations are the same as for AS1
LP2=3	The radius of the return circle is 20 mm	The length of the returning path is along the line to approach







The easiest way to mill a slot is to use the SLOT2 cycle. The cycle can be found and parameterized via the "Mill." SK.




📕 Mill.

The relevant cycle can be found using the vertical SKs on the right.



Select "slot" using the vertical SKs and parameterize the cycle according to requirement.



With the "OK" SK, the values and cycle call will be transferred to the part program as shown below. This will perform milling at the position defined in the cycle.




actual effect



Create Part Program Part 2

Basic Theory




N210 SLOT2(50.00000, 0.00000, 2.00000, , 3.00000, 3, 30.00000, 6.00000, 38.00000, 70.00000, 20.00000, 165.00000, 90.00000, 300.00000, 300.00000, 3.000000, 3.020000, 2000, 5.00000, 250.00000, 300.000000,)

For descriptions of RTP, RFP, SDIS, DP and DPR, please see page 40 For descriptions of CPA, CPO and RAD, please see page 45 For descriptions of FFD and FFP1, please see page 48

Parame- ters	Meanings	Remarks
NUM=3	Three slots on the circle	
AFSL=30	Angle slot length is 30°	AFSL and WID jointly
WID=6	Slot width is 6 mm	decide the shape of the slot in the plane
STA1=165	Start angle, angle between the effective work piece horizontal coordinate in positive direction and the first circle slot is 165°	
INDA=90	Incremental angle, angle between the slots is 90°	INDA=0, cycle will calculate the incremental angle automatically
MID=3	Maximal depth of one feed is 3 mm	MID=0 → complete the cutting of the slot depth
CDIR=3	Milling direction G3 (in negative direction)	Evaluate value 2→use G2 (in positive direction)
FAL=0.2	Slot side, finishing allowance is 0.2 mm	
VARI=0	The type of machining is complete machining	VARI=1→roughing VARI=2→finishing
MIDF=5	Maximal feed depth of the finishing is 5 mm	
FFP2=250	Feed rate of finishing is 250 mm/min	
SSF=3000	Spindle speed for finishing is 3000 mm/min	
▲ If FFP	2/SSF are not specified, then use the feed rate/spind	le speed of rotation as default
FFCP=	Feed rate at the center position on the circle path, unit is mm/min	







																		_	_	






Content

Module Description

This unit describes how to simulate a part program before executing it in AUTO mode.

Module Content



End

SEQUENCE



Step 1


The part program must be opened using the "Program Manager" on PPU.

	14:05:35 2012/04/25
N:\MPF\DEMO_PART_1.MPF 1	Execute
10 G17 G90 G54 G71 ¶	LACCULC
N20 SUPA G00 Z300 D0 ¶	
N30 SUPA G00 X300 Y300 ¶	Renumber
N40 T1 D1 1	Rendriber
N50 MSG("Please change to Tool No 1") ¶	
N60 M05 M09 M00 ¶	Search
N70 S4000 M3 ¶	Search
;======================Facemilling start ¶	
N80 CYCLE71(50.00000, 2.00000, 2.00000, 0.00000, 0.00000, 0.00000,	Mark
70.00000, 100.00000, 0.00000, 2.00000, 40.00000, 2.00000, 0.20000, 5	On
00.00000, 41, 5.00000) ¶	
N90 54500 N3 1	C
N100 CYCLE71(50,2,2,0,0,0,70,100,0,2,40,2,0.2,300,22,5) ¶	Сору
;======================Facemilling end ¶	
N110 SUPA G00 Z300 D0 ¶	
N120 SUPA G00 X300 Y300 ¶	Paste
;=======================Pathmilling start ¶	
N130 T3 D1 ¶	
N140 MSG("Please change to Tool No 3") ¶	
N150 N05 N09 N00 T	
N160 S5000 M3 G94 F300 ¶	
Edit 🛃 Cont. 🛃 Drill. 🛃 Mill. 💽 Active 🚅 Simu.	Re- comp.






SEQUENCE



Step 3

Press the "CYCLE START" key on the MCP.






Press the "Edit" SK on the PPU to return to the program.



End







																		_	_	





Content

Unit Description

This unit describes how to load the program in "AUTO" mode and test the part program at fixed speed.

Unit Content



SEQUENCE




Before the part program can be loaded and executed in AUTO mode, it must be tested using the simulation function mentioned previously!

10 G17 G90 N20 SUPA G0				1	14:05:35 2012/04/25 Execute Renumber
Press th	ne "Execute" S	K on the P	PU.		Execute
M Auto N: MPF \DEMO	Position 0.000	Dist-to-go 0.000 mm	т,ғ,s Т 1	SIEMENS D 1	14:11:53 2012/04/25 G function Auxiliary function
mode w program displaye	trol is now in <i>i</i> ith the current of storage path and the AU <i>I</i> CP is on.	opened being		HAADD WHEEL JO AUTO	

 \wedge

Now the program is ready to start and the actual operation will be described in the next section!






SIEMENS

SEQUENCE




Before executing the "Dry Run", please change the offset value appropriately for the real workpiece size in order to avoid cutting the real workpiece during the dry run and avoid unnecessary danger!


Note: The following operation is based on the finished "program execution"



Use the traversing key to move to the required position. The position is now highlighted.

Enter the required feedrate in mm/min, enter "2000" in the example.





Note: The "DRY" symbol is shown and the "Dry run feedrate" SK is highlighted in blue.

Press the "Back" SK on the PPU.





Make sure the feedrate override on the MCP is 0%.

Press "Door" on the MCP to close the door of the machine. (If you don't use this function, just close the door in the machine manually.)

Press "CYCLE START" on the MCP to execute the program.



Turn the feedrate override gradually to the required value.




After finishing the dry run, please turn the changed offset back to the original value in order to avoid affecting the actual machining!

Operating and Programming — Milling





																		_	_	






Content


Unit Description


This unit describes how to use the Time counter function and how to machine pieces and the compensation setting for the tool wear.


Unit Content



Basic Theory









SEQUENCE



The tool wear compensation must distinguish the direction of compensation clearly!

Step 1

Press the "Offset" key on the PPU.

Press the "Tool wear" SK on the PPU.



Tool wear

Use the direction keys to select the required tools and their edges.

	→ Auto						14:32:25 2012/04/2
Tool					Active tool no	1 D 1	
Type	Т	D	Wea	r			_
			Length1	Radius			Milling
#	1	1	0.000	0.000			tool
Ĩ,		г	0.000	0.000		-	
Ū	2	1	0.000	0.000		-	Drilling
Ě.	3	1	0.000	0.000			tool
Ũ	4	1	0.000	0.000			
Ũ	5	1	0.000	0.000			Tapping tool
j,	6	1	0.000	0.000			001
ñ	7	1	0.000	0.000			Ball end
Ø H	8	1	0.000	0.000			mil.tool
			_	_			Back
To	ol 1 st		Tool Jear		♥ Work R offset R var.	SD Sett.	GUD User data

Step 2

Set the tool length wear parameter of axis X in "Length X", the sign determines the direction of wear compensation.

Set the tool length wear parameter of axis Z in "Length Z", the sign determines the direction of wear compensation.

Positive value: The tool moves away from the workpiece Negative value: The tool moves closer to the workpiece

Press "Input" on the PPU to activate the compensation.



Set the tool radius wear parameter in "Radius", the sign determines the direction of wear compensation.

Positive value: tool is away from workpiece (set radius bigger than real one)

Negative value: tool is close to workpiece (set radius smaller than real one)

Press "Input" on the PPU to activate the compensation.



Type	т	D	Wea	r				<u> </u>
			Length1	Radius				
d la	1	1	0.220	1.200			п	Milli tool
1		2	0.000	0.000			н	
ñ	2	1	0.000	0.000			1	Drill
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	3	1	0.000	0.000				tool
8	4	1	0.000	0.000				_
Ŭ	5	1	0.000	0.000				Tappi tool
	6	1	0.000	0.000				
0	7	1	0.000	0.000				Ball
	8	1	0.000	0.000				mil.t
								_
	_	_						
-	-			been activate	_	_		Back



																		_	_	






Content


Unit Description

This unit describes how to restart the part program after a tool has been changed due to damage, or remachining has to be performed.

Unit Content



SEQUENCE



Operating and Programming — Milling





SEQUENCE

Pres	s the "Bac	k" SK o	n the PPL	J. 🗖	\Rightarrow	•	K Back
Μ	Auto	107			CIER		14:21:24 2012/05/02
N:\MPF	<pre>\DEMO_PART_1 . SKP DRY ROV</pre>	MPF MA1_PRT_SB			SIEN	IENS	G function
MCS	Posit		Dist-to-go	T,F,S			
Х	0	. 000	0.000 mm	Τ3		DØ	Auxiliary function
Y	0	. 000	0.000 mm	F	0,000 0.000	100% nn/nin	Axis feedrate
Ζ	0	. 000	0.000 mm	S1	0,0 0.0	100% 0	
601	654		660				Tine
Block d	display	Curren	t program :DE	MO_PART_1	.MPF		counter
	SUPA 600 2300		milling end¶				Act. val.
	SUPA 600 X300						REL
	T4 D1¶ MSG("Please d		T1 N- 4")f				Act. val.
	M05 M09 M001	nange to	1001 10 4 71				Work(WCS)
;====		====Circ	ular pocketmi	lling star	•t¶		Act. val.
							Mach(MCS)
Act.				Block search		🚽 Real. simu.	Prog.



The feedrate override must always be set to 0%! Make sure the correct tool is selected before continuing!

Press the "CYCLE START" key on the MCP to execute the program.



M , A	U10208	🖄 Channe 1	1 continue	program	with NC start			
N:\MPF\D	EMO_PART_1 .	MPF			SIEME	NS	G	i
👩 Stop	SKP DRY ROV I						function	i.

Alarm 010208 is shown at the top prompting to press the "CYCLE START" key to continue the program.

Press the "CYCLE START" key on the MCP to execute the program.


Turn the feedrate override on the MCP gradually to the required value.

N:\MPF\	Auto Please change to T Auto DEMO_PART_1 .MPF	ool No 4		SIEN	MENS	G function
MCS	Position	Dist-to-go	T,F,S			
- X	0.175	-8.691 mm	T 4		D 1	Auxiliary function
۰Y	61.344	-6.664 mm		3 00,000 300.000	100% mm/min	Axis feedrate
Ζ	-0.267	0.000 mm	S1	500,0 5000.0	100% 0	
GØ3 Block d	654 Lice Leur Current	G64 program :DEMO	DODT 1	MDF		Tine counter
N370	55000 M31					Act. val.
	POCKET4 50.00000, 0.000 SS500 M31	300, 2.00000,	-5.00000	, 22.000	00, 38.	REL Val.
	55500 M31 POCKET4(50.00000, 0.00	AAA. 2.00000.	-5.00000	. 22.000	AA. 38.	
	;========================					Act. val.
	SUPA G00 Z300 D01					Work(WCS)
N430	SUPA 600 X300 Y300¶					Act. val.
						Mach(MCS)
ActV	al		lock earch		🛃 Real. simu.	Corr. Prog.





																		_	






Content


Unit Description

This unit describes how to perform simple tasks on the machine and provides some additional information which may be required to operate the machine correctly.

Unit Content



SEQUENCE



Press the "Save" SK on the PPU.

Press the "Back" SK on the PPU.


K Back

Save

		Ν.
	Additional	
	Information	
$\mathbf{\mathbf{N}}$	Part 1	
		/


SIEMENS

SEQUENCE



If there is a problem during transfer of the part program, a window will be displayed.






Check the interface setting and start the communication software to send the program from PC.

(Press "Send Data" on SINUCOM PCIN to send data.)


The PPU will display a window showing the progress of the transfer.

Receiv	ving of data	19200,8,1,NONE
File: From	_N_DEMO_PART_1_MPF R5232	
То	/_N_MPF_DIR	
Bytes:	903	





SEQUENCE





The PPU has an online help which shows the contents of standard documents.

Press the "Help" key on the PPU.



EXIT

Press the "Cur. Topic" SK on the PPU.



The help information related to the current topic will be shown on screen.

Press the "OEM Manual" SK on the PPUE



The online help manual of the OEM will be shown on the screen.

Press the "TOC" SK on the PPU.



The online help from the Siemens manual will be shown.






SEQUENCE





"Face cutting" is used to cut the oversized materials on the rough face before starting to machine.

Step 1














The arithmetic parameters are used in a part program for value assignment, and also for some necessary value calculations. The required values can be set or calculated by the control system during program execution. Some of the common arithmetic functions are shown below:

Note:

Reprocessing stop

Programming the STOPRE command in a block will stop block preprocessing and buffering. The following block is not executed until all preprocessed and saved blocks have been executed in full. The preceding block is stopped in exact stop (as with G9).

Press the "Offset" key	on the PPU				
Press the "R var." SK	on the PPU			R R var.	
N40 047 000 054			WCS	Position	Repos offset
N10 G17 G90 G54			Х	-10.000	0.000 mm
N20 T1 D1					
N30 S2500 M03 M08			Y	0.000	0.000 mm
N40 G00 X-10.0 Y0 Z	10				A.888 mm
N50 R1=0 R2=0 R3=0)		Ζ	10.000	0.000 MM
N60 STOPRE			R variab	les	
N70 M00			RØ	0.000000	
N80 R1=1		\searrow	R1	0.00000	
			R2	0.00000	
N90 STOPRE			R3	0.00000	
N100 M00			R4	0.00000	
N110 R2=2	→ `		RS	0.00000	
N120 STOPRE	\sim		R variab	les	
			RØ	0.00000	-
N130 M00	. N		R1 82	1.00000	
N140 R3=R1+R2			RZ R3	0.00000	
N150 STOPRE			R4	0.00000	
N160 G00 X=R3		\mathbf{N}	RS	0.00000	
N170 M30		\sim	R variab		
	1	X	RØ		
			R1	0.00000	
	$1 $ λ		RZ	2.00000	
	· `		R3	0.00000	
		\mathbf{N}	R4	0.00000	
	+		RS	0.00000	
WCS Position	Repos offset	$ \rangle$	R variab	les	
X 3.000	0.000 mm	- 4	RØ	0.00000	
X 3.000			R1	1.00000	
Y 0.000	0.000 mm		R2	2.00000	1
0.000			R3	3.00000	
7 10 000	0.000 mm		R4	0.00000	
2 10.000			RS	0.00000	







You can change the time on the control if required when the clocks changes from summer time to winter time.


☆


Press "Shiff" and "Alarm" on the PPU simultaneously.

Make sure the password is set to the "CUSTOMER" access level.


Press the '	Date time" SK on	the PPU.	> Date
Date and Time			0 1110
Date and Tir	e setting		
Current Format	2012/04/25	15:12:26	
New	<mark>0000</mark> /00 /00	00 :00 :00	

Enter a new "Date" and "Time".





Operating and Programming — Milling





Press the "OK" SK on the PPU.



Do	not	operate	or	switch	off	1



ок 🗸



When a machine has a manual gearbox on the spindle, it is the responsibility of the operator to change gear at the correct place in the part program.

If the machine tool manufacturer has fitted an automatic gearbox, the following M-codes can be used to change gear in the part program:

Gear stages M40, M41, M42, M43, M44 and M45 are available.

M40	Automatic gear selection
M41	Gear stage 1
M42	Gear stage 2
M43	Gear stage 3
M44	Gear stage 4
M45	Gear stage 5

Example:

The machine tool manufacturer specifies a speed range for each gear stage:


S0500	Gear stage 1 → M41
S4001200	Gear stage 2 → M42
S10002000	Gear stage 3 → M43

If the operator is manually selecting the gear stage in the part program, it is the operator's responsibility to select the correct gear stage according to the required speed.



Notes

																		_	_	






Content

Unit Description


This unit describes how to perform simple tasks on the machine and provides some additional information which may be required to operate the machine correctly.


Part 2

Unit Content



SEQUENCE









The M function initiates switching operations, such as "Coolant ON/ OFF". Various M functions have already been assigned a fixed functionality by the CNC manufacturer. The M functions not yet assigned are reserved for free use of the machine tool manufacturer.

With H functions, the meaning of the values of a specific H function is defined by the machine tool manufacturer.


M codes and H functions created by the OEM should be backed up by the machine tool manufacturer.

Specified M function	Explanation	Specified M function	Explanation
M0	Stop program	M6	Tool change
M1	Stop program with conditions	M7 / M8	Coolant on
M2	End program	M9	Coolant off
M30	End program and back to the beginning	M40	Select gear stage automatically
M17	End subprogram	M41~M45	Change spindle gear
M3 / M4 / M5	Spindle CW/CCW/ Stop		



Frequently used machining sequences, e.g. certain contour shapes, are stored in subprograms. These subprograms are called at the appropriate locations in the main program and then executed.

Subprogram for positions of the four pockets.



Example

The structure of a subprogram is identical to that of the main program, but a subprogram contains M17 - end of program in the last block of the program sequence. This means a return to the program level where the subprogram was called.

The subprogram should be given a unique name enabling it to be selected from several subprograms. When you create the program, the program name may be freely selected. However, the following rule should be observed:


The name can contain letters, numbers and underscores and should be between 2 and 8 characters long.

Example: LRAHMEN7



Additional Information Part 2

SEQUENCE



Subprograms can be called from a main program, and also from another subprogram. In total, up to eight program levels, including the main program, are available for this type of nested call.



In addition to the common specification in Cartesian coordinates (X, Y, Z), the points of a workpiece can also be specified using polar coordinates.

Polar coordinates are also helpful if a workpiece or a part of it is dimensioned from a central point (pole) with specification of the radius and the angle.

The polar coordinates refer to the plane activated with G17 to G19. In addition, the third axis perpendicular to this plane can be specified. When doing so, spatial specifications can be programmed as cylindrical coordinates.

The polar radius RP= specifies the distance of the point to the pole. It is saved and must only be written in blocks in which it changes, after the pole or the plane has been changed.

The polar angle AP= is always referred to the horizontal axis (abscissa) of the plane (for example, with G17: X axis). Positive or negative angle specifications are possible. The positive angle is defined as follows: Starting from the plus direction of X axis and rotates CCW.

It is saved and must only be written in blocks in which it changes, after the pole or the plane has been changed.



Additional Information Part 2


Basic Theory

G110	Pole specification relative to the setpoint position last programmed (in the plane, e.g. with G17: X/Y)
	(when using G110, please always take the current position of the
	tool as the reference point to specify the new pole)
G111	Pole specification relative to the origin of the current workpiece

- coordinate system (in the plane, e.g. with G17: X/Y)
- G112 Pole specification, relative to the last valid pole; retain plane

Programming example

N10 G17 N20 G111 X17 Y36 AP=45 RP=50	; X/Y plane ; pole coordinates in the current workpiece coordinate system
 N80 G112 X35.35 Y35.35 AP=45 RP=27.8 N90 AP=12.5 RP=47.679	; new pole, relative to the last pole as a polar coordinate ; polar coordinate
N100 AP=26.3 RP=7.344 Z4	; polar coordinate and Z axis (= cylinder coordinate)





The programmable workpiece offsets TRANS and ATRANS can be used in the following cases:

- For recurring shapes/arrangements in various positions on the workpiece
- When selecting a new reference point for dimensioning

This results in the current workpiece coordinate system.


TRANS X...Y... Z... ; programmable offset (absolute)


ATRANS X...Y... Z... ; programmable offset, additive to existing offset (incremental)

TRANS ; without values, clears old commands for offset

Programming example	
N20 TRANS X20.0 Y15.0	
L10	

programmable offset subprogram call










The programmable rotation ROT, AROT can be used:

The rotation is performed in the current plane G17, G18 or G19 using the value of RPL=...specified in degrees.

ROT RPL=	;	programmable rotation offset (absolute).
AROT RPL=	;	programmable offset, additive to existing offset
(incremental)		
ROT	;	without values, clears old commands for offset

N10 G17

N20 AROT RPL=45	additive 45 degree rotation
L10	subprogram call






A scale factor can be programmed for all axes with SCALE, ASCALE. The path is enlarged or reduced by this factor in the specified axis. The currently set coordinate system is used as the reference for the scale change.


SCALE X...Y... Z... ; programmable rotation offset (absolute) ASCALE X...Y... Z... ; programmable offset, additive to existing offset (incremental)

If a program contains SCALE or ASCALE, this must be programmed in a separate block.

Programming example N10 G17 N20 SCALE X2.0 Y2.0

N20 SCALE X2.0 Y2.0 L10 ; contour is enlarged two times in X and Y subprogram call










This describes and analyzes the additive offset, coordinate rotation, scaling functions mentioned above.


Machining target dimension drawing and the final effect are as follows:



In this example, the positive direction of the XY coordinate axis is different when machining each groove! Drawing 1—original workpiece machining Drawing 2—coordinate rotates 100° Drawing 3—1 Drawing 2 along X axis mirror image ②Coordinate rotates 20° Drawing 4—1 Drawing 3 along Y axis moves 60 in negative direction ②enlarge 1.3 times in X and Y direction

N10	SUPA G00 Z300 D0
N15	SUPA G00 X0 Y0
N20	G17 T1 D1
N25	MSG ("change to 1 tool")
N30	M5 M9 M00
N35	S5000 M3 G94 F300
N40	G00 X-28 Y 30
N45	G00 Z2
N50	LAB1:
N65	POCKET3(50, 0, 2, -5, 30, 15, 3, -28,
30, 0	, 5, 0, 0, 300, 100, 0, 11, 5, , , 5, 3,)
N70	LAB2:
N75	M01
N80	ROT RPL=-100
N85	REPEAT LAB1 LAB2 P1
N90	M01
N95	AMIRROR X=1
N100	AROT RPL=-20
N105	M01
N110	REPEAT LAB1 LAB2 P1
N115	AROT RPL=10
N120	ATRANS Y-60
N125	AROT RPL=-10
N130	ASCALE X1.3 Y1.3
N135	REPEAT LAB1 LAB2 P1
N140	M30

SUPA→cancel all settable offsets N10 N15 N20 coordinate plane G17, use tool 1 N25 N30 N35 N40 N45 N50 LAB1:milling start sign milling rectangular groove (depth 5 mm, N65 length 30 mm, width 15 mm, corner radius 3 mm, groove datum coordinate (X-28,Y30), groove longitudinal axis and plane X axis clamping angle 0°) N70 LAB2:milling aroove end sign N75 N80 coordinate axis rotates 100° in positive direction N85 machining the same groove at the new position N90 N95 along the new X axis to change the mirror image N100 coordinate axis rotates -20° in positive direction N105 N110 machining the same groove at the new position N115 coordinate axis rotates - 10° in negative direction N120 Y axis coordinate moves 60 in negative direction N125 N130 groove enlarged 1.3 times in the X, Y direction N135 machining the same groove at the new position N140 end









NC programs process their blocks in the sequence in which they were arranged when they were written. The processing sequence can be changed by introducing program jumps. The jump destination can be a block with a label or with a block number. This block must be located within the program. The unconditional jump command requires a separate block.

- GOTOF+ label: Jump forward (in the direction of the end block of the program)
- GOTOB+ label: Jump backward (in the direction of the start block of the program)
- Label: Name of the selected string (standing for the required jump program block) or block number


Program execution




Unconditional jump example




SIEMENS



When "SKP" is displayed (red circle), the skip function has been activated. After activating "SKP", using "/" at the beginning of the program string (shown in purple circle), the string will be skipped without influencing the execution.







Basic Theory

You can use the calculator to calculate contour elements, values in the program editor, tool offsets and workpiece offsets and enter the results on the screen

Press the "=" SK on the PPU.

=

Calculator	
7 8 9 7	SIN(x) C
4 5 6 *	COS(x)
123+	1577 R
0	x ² Q

С Delete ~ Back Accept

Press this SK to delete the contents in the calculator



Press this SK to exit the calculator screen.

Use this SK to accept the input and write the values to the required position.

If the input field is already occupied by a value, the calculator will take this value into the input line.

Use the "Accept" SK to enter the result in the input field at the current cursor position of the part program editor. The calculator will then close automatically.



Notes

																		_	_	






Content

Unit Description


This unit shows three typical program examples of frequently used milling cycles and the corresponding machining diagrams with detailed explanations.

Unit Content



Note: All the program examples in this book are only for reference. If you want to perform actual operations, please adjust the tool offset, coordinate moving range, workpiece plane settings, etc. according to the actual machine conditions!

Drawing







Machining Process

N10	G17 G90 G54 G60 ROT
N20	T1 D1; FACEMILL
N30	M6
N40	S4000 M3 M8
N50	G0 X-40 Y0
N60	G0 Z2
; ====	====Start face milling========
N70	CYCLE71(50, 1, 2, 0, -25, -25, 50, 50,
0,1,,	, 0, 400, 11,)
	S4500
N90	CYCLE71(50, 1, 2, 0, -25, -25, 50, 50,
0,1,,	, 0, 400, 32,)
; ====	====End face milling========
N100	G0 Z100
N110	T2 D1 ; ENDMILL D8
N120	M6
N130	S4000 M3
N140	M8 G0 X-13 Y16
N150	G0 Z2
; ====	====Start rectangular pocket rough-
ing===	
N160	_ANF:
N170	POCKET3(50, 0, 2, -5, 13, 10, 4, -13,
16, 0,	5, 0.1, 0.1, 300, 200, 2, 11, 2.5, , , ,
2, 2)	
; ==A	daptive rotation around Z axis==
N180	AROT Z90
N190	_END:

N20 tool 1 is plane milling tool

M	0	n	
IN			
ы	л	n	
IN	4	υ	

N10

N50 N60

; ======Start face milling=======

N70 start point (X-25, Y-25), the length and the width are 50 mm, feedrate 400 mm/ min, along the direction parallel to the X axis to perform roughing. N80

N100 N110 tool 2 is face milling tool, diameter 8 mm

N120 N130 N140

N150

; ===Start 1 rectangular pocket roughing===

N160 _ANF: Milling start sign

N170 milling rectangular groove (depth 5 mm, length13 mm, width 10 mm, corner radius 4 mm, groove base point coordinate (X-13,Y16), angle between groove vertical axis and plane X axis is 0°), feedrate 300 mm/min, milling direction G2, rough machining, use G1 vertical groove center to insert.

; ==Adaptive rotation around Z axis== N180 rotation in positive direction 90° N190 _END: Milling end sign

: =====Repeat rectangular pocket milling 3 times======== N200 REPEAT ANF END P=3 : =====Cancel rotation====== N210 ROT N220 S4500 M3 ; =====Start rectangular pocket finishing======== ANF1: N230 N240 POCKET3(50, 0, 2, - 5, 13, 10, 4, -13, 16, 0, 2.5, 0.1, 0.1, 300, 200, 2, 2, 2.5, , , , 2, 2) ; ==Adaptive rotation around Z axis== AROT Z90 N250 N260 END1: : ======Repeat rectangular pocket milling 3 times=======

- N270 REPEAT _ANF1 _END1 P=3
- N280 ROT
- ; ======Cancel rotation=======

; ====Repeat 2 3 4 rectangular pocket milling 3 times=====

N200 Repeat N160 ~ N190 operation three times

; =====Cancel rotation=======

N210 cancel all the coordinate rotation commands N220

: ===Start ① rectangular pocket finish-

ing===

N230 _ANF1: Milling start sign

N240 milling rectangular groove (depth,

length、width、corner radius、base

point、corner angles are the same as the above parameters), plane feedrate300 mm/ min, depth direction feedrate200 mm/min, milling direction G2, finish machining.

; ==Adaptive rotation around Z axis===

N250 rotation in positive direction 90°

N260 _END1: Milling end sign

; ====Finishing ② ⑧ ④ rectangular pocket milling =====

N270 repeat N230~N260 operation three times

N280 cancel all the coordinate rotation commands

; ====Cancel rotation========



Machining Process

Sample

Program

N290 G0 X0 Y0

: ========Start circular pocket roughing========== N300 POCKET4(50, 0, 2, -5, 7.5, 0, 0, 2.5, 0.1, 0.1, 300, 200, 0, 21, 2, , , 4, 1) N310 S4500 M3 : =========Start circular pocket finishing========= N320 POCKET4(50, 0, 2, -5, 7.5, 0, 0, 5, 0.1. 0.1. 300. 200. 0. 12. 2. . . 4. 1) N330 G0 Z100 : ======Start drilling======= N340 T3 D1 :DRILL D3 N350 M6 N360 S5000 M3 N370 G0 X0 Y0 N380 MCALL CYCLE81(50, 0, 2, -5, 0) N390 HOLES2(0, 0, 10, 45, 60, 6) N400 MCALL N410 M30

N290 back to workpiece zero point ;====Start circular pocket roughing===== N300 milling circular groove (depth 5 mm, radius 7.5 mm, groove base point coordinate (X0,Y0), angle between groove vertical axis and plane X axis is 0°), milling direction is positive, rough machining. N310

; ====Start circular pocket finishing=====

N320 milling circular groove (depth 5 mm, radius 7.5 mm, groove basic point coordinate (X0,Y0), the clamping angle between the groove vertical axis and plane X axis is 0), finish machining allowance 0.1 mm, milling direction is positive, finish machining, use G1 vertical groove center to insert.

N330 G0 Z100

; ======Start drilling========

N340 3 tool is drilling tool diameter 3 mm N350

N360


 $\begin{array}{lll} N370 & \text{back to workpiece zero point} \\ N380 & drilling depth 5 mm, use "MCALL" \\ mode to use command, means drilling position$ $decided by the parameters in N490 \\ N390 & circular line hole forms cycle command$ (circular center point coordinate (X0,Y0), radius10 mm, angle between the line with first holeand circular center point and the X axis inpositive direction is 45°, angle between the $holes is 60°, circular hole number 6 <math display="inline">\uparrow$.) N400 cancel mode use

N410 M30

Drawing



Make sure all the preparations and safety measures have been performed before machining!



Operating and Programming — Milling



SIEMENS

Machining Process

G17 G90 G60 G54 N10 N20 T1 D1 :FACEMILL D50 N30 M6 N40 S3500 M3 N50 G0 X0 Y0 N60 G0 Z2 : =====Start face milling======= N70 CYCLE71(50, 1, 2, 0, 0, 0, 50, -50, . 1.40. 0.1. 300.11.) N80 S4000 M3 N90 CYCLE71(50, 0.1, 2, 0, 0, 0, 50, -50 , , 1, 40, , 0, 250, 32,) : =====Start contour milling====== T2 D2 :END MILL N100 N110 M6 S3500 M6 N120 CYCLE72("CON1:CON1 E". 50. 0. 2. N130 -5, 2, 0.1, 0.1, 300, 300, 11, 42, 1, 4, 300, 1, 4) : =====Start path milling with radius compensation ======= N140 T4 D1 :ENDMILL D10 N150 M6 S4000 M3 N160 G0 X55 Y-15 N170 N180 G0 Z2 G1 F300 Z-8 N190 N200 G42 G1 Y-15 X50 G1 X44 Y-2 RND=2 N210 N220 G1 Y0 X 22

- N230 G40 Y30
- M30 N240

- N10 N20 tool 1 is milling tool, diameter 50 mm N30 N40
- N50 back to workpiece zero point N60

: ======Start face milling======

N70 start point (X0, Y0), the length and the width are 50 mm feedrate 300 mm/min finishing allowance 0.1 mm, along the direction parallel to the X axis to perform the rough machining N80

N90 start point (X0, Y0), the length and the width are 50 mm, feedrate 250 mm/min, finishing allowance 0, along the direction parallel to the X axis to perform the finish machining : ====Start contour milling====== N100 tool 2 is milling tool N110

N130 contour cutting depth 5 mm, all finishing allowances 0.1 mm, the feedrate of surface machining and cutting direction 300 mm/min, use G42 to activate the compensation, use G1 to do rough machining, approaching path is along a straight line. length 4 mm, the parameters of feedrate/path/length in retraction and approach are equal. ; ====Start path milling with radius com-

pensation ===

N140 tool 4 is face milling tool, diameter 10 mm

N150 N160 N170

N120

N180 N190

N200 G42 activate tool radius compensation N210 starts from (X44,Y-2) insert a reverse circle, radius is 2 mm

N220 (X22,Y0) is the reverse circle point N230 G40 cancel tool radius compensation N240

:*******************CONTOUR************ CON1:

:#7 DlaK contour definition begin - Don't change!:*GP*:*RO*:*HD* G17 G90 DIAMOF:*GP* G0 X3 Y3 :*GP* G2 X3.27 Y-40.91 I=AC(-52.703) J=AC(-19.298) :*GP* G3 X46.27 Y-47 I=AC(38.745) J=AC (54.722) :*GP* G1 X42 Y-8 :*GP* X3 Y3 :*GP* :CON.0.0.0000.4.4.MST:0.0.AX:X.Y.I.J :*GP*:*RO*:*HD* :S.EX:3.EY:3:*GP*:*RO*:*HD* :ACW.DIA:0/35.EX:3.27.DEY:-43.91,RAD:60;*GP*;*RO*;*HD* :ACCW.DIA:0/35.DEX:43.EY:-47.RAD:102:*GP*:*RO*:*HD* :LA.EX:42.EY:-8:*GP*:*RO*:*HD* ;LA,EX:3,EY:3;*GP*;*RO*;*HD* ;#End contour definition end - Don't change!:*GP*:*RO*:*HD*

CON1 E::****** CONTOUR ENDS*******

This program is additional description information created by the system automatically after finishing the programming of the rough cutting CYCLE72 and does not affect the system execution.





Sample Program

Drawing



Part of the cycles in the program are taken as examples in Section 5, "Create Part Program Part 2"!





Tool information T1 Milling tool D50 T2 Milling tool D12 T3 Milling tool D10 T4 Milling tool D16

T5 Milling tool D5 T6 Drilling tool D10 T7 Drilling tool D5 T8 Tap D6

Machining Process

N10 G17 G90 G54 G71 SUPA G00 Z300 D0 N20 SUPA G00 X300 Y300 N30 T1 D1 N40 MSG ("Please change to Tool No 1") N50 N60 M05 M09 M00 S4000 M3 N70 : ======Face milling start======= CYCLE71(50, 2, 2, 0, 0, 0, 70, 100, N80 0. 2. 40. 2. 0.2. 500. 41. 5) S4500 M3 N90 N100 CYCLE71(50, 2, 2, 0, 0, 0, 70, 100, 0, 2, 40, 2, 0.2, 300, 22, 5) : =======Face milling end======== N110 SUPA G00 Z300 D0 N120 SUPA G00 X300 Y300 : ======Path milling start======= N130 T3 D1 N140 MSG("Please change to Tool No 3") M05 M09 M00 N150 N160 S5000 M3 G94 F300 N170 G00 X-6 Y92 G00 72 N180 G01 F300 Z-10 N190 G41 Y 90 N200 N210 G01 X12 RND=5 N220 G01 Y97 CHR=2 N230 G01 X70 RND=4 N240 G01 Y90 N250 G01 G40 X80 N260 G00 Z50 ; ======Path milling end=======

N10 N20 N30 N40 N50 hint: change to tool 1 N60 N70

; ======Face milling start======

N80 start point (X0,Y0), machining length: X →70 mm, Y→100 mm, angle between vertical axis and X axis is 0°, finishing allowance 0.2 mm, feedrate 500 mm/min, along the alternate direction parallel to the Y axis to perform the finishing

N90

N100 repeat N80 contour process, the difference in the feedrate is 300 mm/min along the single direction parallel to the Y axis to perform the finishing

: =======Face milling end======= N110 N120 : =====Path milling start======== N130 N140 hint: change to tool 3 N150 feedrate 300 mm/min N160 N170 N180 N190 left side radius compensation N200 circle, milling radius is 5 mm N210 incline, milling side length is 2 mm N220 N230 N240 N250 cancel tool radius compensation N260 : ======Path milling end======





Machining Process

N270 SUPA G00 Z300 D0 N280 SUPA G00 X300 Y300 N290 T4 D1 N300 MSG ("Please change to Tool No 4") N310 M05 M09 M00 : ===Circular pocket milling start==== S5000 M3 N320 N330 POCKET4(50, 0, 2, -5, 22, 38, 70, 2.5. 0.2. 0.2. 300. 250. 0. 21. 10. 0. 5. 2. 0.5)N340 S5500 M3 N350 POCKET4(50, 0, 2, -5, 22, 38, 70, 2.5. 0.2. 0.2. 250. 250. 0. 22. 10. 0. 5. 2. 0.5) ; ===Circular pocket milling end==== N360 SUPA G00 Z300 D0 N370 SUPA G00 X300 Y300 N380 T5 D1 MSG ("Please change to Tool No 5") N390 N400 M05 M09 M00 : ======Slot milling start======= N410 M3 S7000 N420 SLOT2(50, 0, 2, . 3, 3, 30, 6, 38, 70, 20, 165, 90, 300, 300, 3, 3, 0.2, 0, 5, 250. 3000.) : ======Slot milling end=======

N270 N280 N290 N300 hint: change to tool 4

- N310
- ; ====Circular pocket milling start=== N320

N330 milling circular groove (depth 5 mm, radius 22 mm, groove center coordinate (X38,Y70), finishing allowance 0.2 mm, plane machining feedrate 300 mm/ min, milling in positive direction, along helical path insert to do rough machining, helical path radius 2 mm, insert depth 0.5 mm)

N340

N350 repeat N370 milling process, the difference is the machining allowance. ; ====Circular pocket milling end=== N360 N370

N380

N390 hint: change to tool 5 N400

; =====Slot milling start======

N430 SUPA G00 7300 D0 SUPA G00 X300 Y300 N440 : =====Contour milling start====== N450 T2 D1 N460 MSG ("Please change to Tool No 2") M05 M09 M00 N470 S5000 M3 N480 N490 CYCLE72("CONT1:CONT1 E", 50, 0, 2. -5. 5. 0. 0. 300. 100. 111. 41. 12. 3. 300, 12, 3) : =====Contour milling end====== N500 SUPA G00 Z300 D0 N510 SUPA G00 X300 Y300 : =Rectangular pocket milling start== N520 T2 D1 MSG ("Please change to Tool No 2") N540 M05 M09 M00 S6500 M3 N560 POCKET3(50, 0, 1, -3, 40, 30, 6, 36, 24.1, 15, 3, 0.1, 0.1, 300, 300, 0, 11, 12.8.3.15.0.2) N570 POCKET3(50, 0, 1, -3, 40, 30, 6, 36. 24.1. 15. 3. 0.1. 0.1. 300. 300. 0. 12. 12, 8, 3, 15, 0, 2) : ==Rectangular pocket milling end==

N430 N440 ; =====Contour milling start====== N450 N460 hint: change to tool 2 N470 N480 N490 contour cutting depth 5 mm, surface machining feedrate 300 mm/min, use G41 to activate compensation. use G1 to do rough

machining, back to the machining plane at the end of the contour, approach path is along 1/4 circle in space, length 3 mm, the parameters of feedrate//path/length for retraction and approach are equal.

; =====Contour milling end======= N500

N510

; =Rectangular pocket milling start== N520

N530 hint: change to tool 2

N540 N550

N560 milling rectangle groove (depth 3 mm, length 40 mm, width 30 mm, corner radius 6 mm, groove base point coordinate (X36,Y24.1), angle between groove vertical axis and plane X axis is 15°), finishing allowance 0.1 mm, feedrate surface machining and cutting direction machining is 300 mm/min, milling in positive direction, rough machining, use G1 vertical groove center to insert.

N570 repeat N600 milling process, the difference is the machining allowance. ; ==Rectangular pocket milling end==





Machining Process

N580 SUPA G00 Z300 D0 N590 SUPA G00 X300 Y300 : ======Centering start======= N600 T6 D1 N610 MSG ("Please change to Tool No 6") M05 M09 M00 N620 S6000 M3 N630 G00 Z50 X36 Y24.1 N640 MCALL CYCLE82(50, -3, 2, -5, 0, 0.2) N650 N660 HOLES2(36, 24.1, 10, 90, 60, 6) N670 X36 Y24.1 N680 MCALL : Modal Call OFF : ======Centering end======== N690 SUPA G00 Z300 D0 N700 SUPA G00 X300 Y300 : ======Drilling start======== N710 T7 D1 N720 MSG ("Please change to Tool No 7") N730 M05 M09 M00 N740 S6000 M3 N750 MCALL CYCLE83(50, -3, 1, , 9.24, ,5, 90. 0.7. 0.5. 1. 0. 3. 5. 1.4. 0.6. 1.6) N760 HOLES2(36, 24.1, 10, 90, 60, 6) N770 X36 Y24.1 MCALL ; Modal call Off N780 : ======Drilling end=========

N700

- P				

N750 CYCLE83 mode recall command active →drilling depth 9.24 mm, first drilling depth 5 mm, degression 90, last drilling depth (delayed milling) stops for 0.7 s, stops at the start point for 0.5 s, first drilling feed modules is 1, select Z axis as the tool axis, machining type is delayed milling, tool axis is Z axis, minimal depth 5 mm, every retraction is 1.4 mm, drilling depth stops for 0.6 s, reinsert lead distance 1.6 mm N760 hole arrangement circular center coordinate (X36, Y24.1), circular radius 10

mm, start angle 90°, angle between the holes is 60°, circular hole number 6 N770 continue drilling with (X36,Y24.1) as the center point

N780 cancel mode recall instruction

: =======Drilling end=========

N790 SUPA G00 Z300 D0 N800 SUPA G00 X300 Y300 : =======Tapping start======== N810 T8 D1 N820 MSG ("Please change to Tool No 8") N830 M05 M09 M00 N840 S500 M3 N850 MCALL CYCLE84(50, -3, 2, , 6, 0.7, 5, , 2, 5, 5, 5, 3, 0, 0, 0, 5, 1.4) N860 HOLES2(36, 24.1, 10, 90, 60, 6) N870 X36 Y24.1 N880 MCALL : Modal call Off : ======Tapping end========= N890 SUPA G00 Z500 D0 N900 SUPA G00 X500 Y500: : =======Move to the change position Ready to start next program or repeat

N910 M30

N790 N800 ; =====Tapping start====== N810

N820 hint: change to tool 8

N830 N840

N850 CYCLE84 mode recall active→drilling

depth 6 mm, last tapping depth (delayed milling) stops for 0.7 s, after the cycle, the spindle M5 stops, machining dextrorotation thread, size 2 mm

, spindle stop position is 5°, the tapping speed and the retraction speed of the spindle are 5 r/min, select Z axis as the tool axis, incremental drilling depth 5 mm, retraction value is 1.4 mm

N860 hole arrangement circular center coordinate (X36,Y24.1), circular radius 10 mm, start angle 90°, angle between the holes is 60°, circular hole number 6 N870 continue drilling with X36,Y24.1) as the center tapping N880 cancel mode recall instruction

; ======Tapping end=====

N890 N900

; =====Move to the change position Ready to start next program or repeat ====== N910



Sample Program

Machining Process

N1100 :************CONTOUR********** N1110 CONT1: N1120 ;#7 DlgK contour definition begin -Don't change!;*GP*;*RO*;*HD* N1130 G17 G90 DIAMOF:*GP* N1140 G0 X7 Y0 :*GP* N1150 G1 Y61.35 ;*GP* N1160 G2 X13.499 Y86 I=AC(57) J=AC (61.35) :*GP* N1170 G1 X63 RND=2 :*GP* N1180 Y0 :*GP* N1190 ;CON,0,0.0000,4,4,MST:0,0,AX:X,Y,I,J, TRANS:1;*GP*;*RO*;*HD* N1200 :S.EX:7.EY:0:*GP*:*RO*:*HD* N1210 :F.LFASE:0:*GP*:*RO*:*HD* N1220 ;LU,EY:61.35;*GP*;*RO*;*HD* N1230 ;ACW,DIA:210/0,EY:86,AT:0,RAD:50;* GP*:*RO*:*HD* N1240 ;LR,EX:63;*GP*;*RO*;*HD* N1250 ;R,RROUND:2;*GP*;*RO*;*HD* N1260 ;LD,EY:0;*GP*;*RO*;*HD* N1270 ;#End contour definition end - Don't change!;*GP*;*RO*;*HD* N1280 CONT1_E:;************ CONTOUR FNDS ***********

This section is additional description information created by system automatically after finishing the programming of the rough cutting CYCLE95 and does not affect the system execution.




Notes



Notes

																		_	_	






Content

Unit Description

This unit describes the ISO operating functions in 808D, compares the similarities and differences of the machining code in DIN mode and ISO mode and shows how to transfer and implement the ISO machining program.

Unit Content



Basic Theory



Siemens standard machining codes are implemented in DIN mode. The 808D also provides also provides appropriate functions for implementing the ISO commands, but the ISO mode must be activated during operation.

ISO function switch

Method 1


Press the "Shift" + "System - Alarm" keys on the PPU. Input the manufacturer's password ("SUNRISE")

Press the "ISO mode" SK on the right.




A dialog box appears prompting whether to activate the new setting. Select the "OK" SK to activate it.









After pressing "OK", the system restarts automatically. After restarting, press "Shift" + "System - Alarm" again and if the symbol in the red circle appears, ISO mode is already activated.

1	ISO Ref	Roint					15:45:42 2012/04/26
(Machine	nfigurati	on				Set
ito-	No.	Axis inde:		Axis type	Drive n	mber	password
10-	1	1	×	Linear axis			Change
	2	2	Y	Linear axis			password
	з	з	z	Linear axis			Delete
,	4	4	SP	Spindle			password
n							Change
9							language
ed							
						(ISO node
-							
4							Save
<i>.</i>	Start	Mach.	IV Serv.	nic Serv.	📴 Sys .	Date	
	-up	MD data	displ.	tc PLC 🌏 Serv.	. El data	⊖ time	Series archiv

A red ISO appears at the top of the screen and the ISO mode button on the right is highlighted in blue.

Method 2

When using method 2 to activate the ISO mode, it will exit ISO mode and return to the default
DIN mode via "Reset" button or after finishing the machining program.

Insert G291 in the first line of the ISO part program to be executed and insert G290 in front of M30.

 NB 6221
 A

 NS 617 670 654 671 11
 A

 N20 11 H1
 A


 N25 N56("Tool No 1 in use")1
 mand.

 N3554000 H31
 separ.

 N45 6420 H31
 0.00000, 2.00000, 2.00000, 0.00000, 0.00000, 0.00000

G291/G290 commands must be set separately in a line!

If ISO is displayed at the top of the screen, it is activated.




All the ISO codes described in this unit can be implemented in the ISO mode of the 808D system!

Brief description of typical, frequently used ISO codes

ISO code	Description	Compare with DIN
G00	Orientation (rapid traverse)	As DIN
G1	Linear difference	As DIN
G17/G18/G19	XY plane / ZX plane / YZ plane	As DIN
G20/G21	Input in inch/mm	G70/G71
G41/G42/G40	Left tool tip radius compensation / right tool tip radius compensation / cancel tool radius compensation	As DIN
G54 ~ G59	Select workpiece coordinate system	As DIN
G80	Cancel fixed cycle	
G90/G91	Absolute/incremental programming	
G94/G95	Feedrate F in mm/min / mm/r	As DIN
S	Spindle speed	As DIN
, R	Reverse circle (note the form there must be ", " before R parameter)	RND
M3/M4/M5	Spindle right / spindle left / spindle stop	As DIN
M98 P _L_	Subprogram call (P+ subprogram name/ L+ times)	Program name + L
M99	End of Subroutine	M17





In DIN mode, the tool length is activated automatically, but in ISO mode, you must activate the tool length via G code.

G43/G44 and G49

Use G43/G44, the tool length compensation value will be activated. G43: Tool length compensation in positive direction G44: Tool length compensation in negative direction G49: Cancel tool length compensation H01→Offset value 20.0 H02→Offset value -30.0 H03→Offset value 30.0 H04→Offset value -20.0


G90 G43 Z100.0 H01; Z will reach 120.0 G90 G43 Z100.0 H02; Z will reach 70.0 G90 G44 Z100.0 H03; Z will reach 70.0 G90 G44 Z100.0 H04; Z will reach 120.0

Note: In DIN mode, you must open the H code list in the tool list. For information on the opening method, please refer to the instructions for H code on page 104

Code G02 and G03

G02 circular interpolation in positive direction

G03 circular interpolation in negative direction You can specify the circle end point in the following X/Z address for both. You can also describe circle radii with I, J, K incremental or use parameter R to specify radii directly.



Method 1 (use incremental to describe circular radius) G92 X200.0 Y40.0 Z0 G90 G03 X140.0 Y100.0 I-60.0 F300.0 G02 X120.0 Y60.0 I-50.0


Method 2 (use parameter R to describe circular radius) G92 X200.0 Y40.0 Z0 G90 G03 X140.0 Y100.0 R60.0 F300 G02 X120.0 Y60.0 R50.0

G98 : Fixed cycle back to the original point G99 : Fixed cycle back to R point G80 : Cancel the fixed cycle Pausing function G04 G04 X5.0→delay 5 s G04 P5→delay 5 ms


N5 G90 T1 M06 N10 M3 S2000: spindle rotation N20 G99 G81 X300 Y-250 Z-150 R-10 F120; after orientation drilling, back to R point N30 X1000. after orientation drilling, back to R point N40 G04 X2.0 ; delay 2 s N50 G98 Y-550 ; after orientation drilling, back to start point N60 G80 : cancel the fixed cycle N70 M5 ; spindle rotation stop N80 M30

When specifying circle radii with parameter R

Circles less than 180° is assigned positive values □→G02 X6.0 Y2.0 R50.0 Circles greater than 180° are assigned negative values □→G02 X6.0 Y2.0 R-50.0







Frequently used letter meanings of typical fixed cycle codes in ISO

P.	Descriptions	Unit	Applied range and note
X/Y	Cutting end point X/Z absolute coordinate values		G73 / G74 / G76 G81 ~ G87 / G89
z	The distance incremental value be- tween R point and the bottom of the hole, or the absolute coordinate value of the bottom of the hole		G73 / G74 / G76 G81 ~ G87 / G89
R	The distance incremental value be- tween the start point plane and R point or the absolute coordinate value of R point		G73 / G74 / G76 G81 ~ G87 / G89
Q	The depth of every cut (incremental value)		G73 / G83
	Offset value (incremental value)		G76 / G87
Р	The delay time at the bottom of the hole	ms	G74 / G76 / G89 G81 ~ G87
F	The feedrate of the cutting	mm/min	G73 / G74 / G76 G81 ~ G87 / G89
к	The repeat times of the fixed cycle		G73 / G74 / G76 G81 ~ G87 / G89

In 808D, the default ISO program feed distance unit is mm! (X100→100mm)

Note: change the parameter 10884=0, to make X100 → 100 um / X100. → 100 mm

Brief introduction of typical fixed cycle codes in ISO mode

For the meaning of letters when programming typical fixed cycles, please refer the figure on the left!

G73 fast-speed deep hole drilling Common programming	M3 S1500	ation example program: ;spindle rotation 373 X0 Y0 Z-15 R-10 Q5 F120
structures:	;	after orientation drill 1st hole, back to R point
G73 X—Y—Z—R—Q—F—	Y-50	after orientation drill 2nd hole, back to R point
к	Y-80	after orientation drill 3rd hole, back to R point
Motion process:		after orientation drill 4th hole, back to R point
(1) Drilling motion (-Z) \rightarrow intermediate feed	G98 Y75	after orientation drill 5th hole, back to R point after orientation drill 6th hole, back to R point
② Motion at the bottom of		; cancel fixed cycle
the hole → none		(0 Y0 Z0 ;back to reference point
③ Retraction motion (+Z)	M5 M30	;spindle rotation stop
→ fast feed		

G74 reverse tapping cycle Common programming structures.

Motion process: (1) Drilling motion (-Z) \rightarrow cutting feed ② Motion at the bottom of the hole → spindle rotation in positive direction

③ Retraction motion (+Z)

→ cutting feed


G74 application example program:

M4 S100 :spindle rotation G90 G99

G74 X300 Y-250 Z-150 R-120 P300 F120

after orientation drill 1st hole, back to R point Y-550 after orientation drill 2nd hole, back to R point Y-750 after orientation drill 3rd hole, back to R pointX1000 after orientation drill 4th hole, back to R pointY-550 after orientation drill 5th hole, back to R pointG98 Y750 :after orientation drill 6th hole, back to R pointG80 ;cancel fixed cycle G28 G91 X0 Y0 Z0 :back to reference point M5 :spindle rotation stop M30

Operating and Programming — Milling





G76 Boring cycle Common programming structures:

G76 X-Y-Z-R-Q-P-F-K

Motion process:

- ① Drilling motion $(-Z) \rightarrow$ cutting feed
- ② Motion at the bottom of the hole →

spindle stop directional

③ Retraction motion (+Z) → fast feed

G76 application example program:

M3 S500 spindle rotation G90 G99 G76 X300 Y-250 Z-150 R-100 Q5 P1000 F120

;after orientation bore 1st hole, then move 5 mm, stop for 1 s at the bottom of the hole, back to the R point.

- Y-50 ;bore 2nd hole (the same as 1st hole)
- Y-80 ;bore 3rd hole (the same as 1st hole)
- X10 ;bore 4th hole (the same as 1st hole)
- Y10 ;bore 5th hole (the same as1st hole) G98 Y-750 ;bore 6th hole, then move 5 mm, stop for 1s at the bottom of the hole back to the start

stop for 1s at the bottom of the hole, back to the star point position plane G80 ;cancel fixed cycle

G28 G91 X0 Y0 Z0 ;back to reference point M5 ;spindle rotation stop M30 G82 Drilling cycle (countersink drilling) Common programming structures:

G82 X—Y—Z—R—P—F—K

Motion process:

- ① Drilling motion (-Z) \rightarrow cutting feed ② Motion at the bottom of the hole \rightarrow pause
- (3) Retraction motion (+Z) \rightarrow fast feed

G82 application example program:

	;spindle rotation X300 Y-250 Z-150 R-100 P1000 F120 on drill 1st hole, stop for 1 s at the bottom
	ck to the R point.
Y-550	;drill 2nd hole (the same as 1st hole)
Y-750	;drill 3rd hole (the same as 1st hole)
X1000	;drill 4th hole (the same as 1st hole)
Y-550	;drill 5th hole (the same as 1st hole)
G98 Y-750	;drill 6th hole, stop for 1 s at the
	nole, back to the start point position plane
G80	;cancel fixed cycle
G28 G91 X0 Y	0 Z0 ; back to reference point
M5 M30	;spindle rotation stop

G81 Drilling cycle (fixed point drilling) Common programming structures:

G81 X—Y—Z—R—F—K

Motion process:

- (1) Drilling motion (-Z) \rightarrow cutting feed
- ② Motion at the bottom of the hole →

none

(3) Retraction motion $(+Z) \rightarrow$ fast feed

G81 application example program:

M3 S2000 ;spindle rotation G90 G99 G81 X300 Y-250 Z-150 R-10 F120

;after orientation drill 1st hole, back to R point Y-550 ;after orientation drill 2nd hole, back to R point

- Y-750 ;after orientation drill 3rd hole, back to R point
- X1000 ; after orientation drill 4th hole, back to R point

Y-550 ;after orientation drill 5th hole, back to R point

G98 Y-750; after orientation drill 6th hole, back to start plane

G80 ;cancel fixed cycle

G83 Drilling cycle (deep hole drilling) Common programming structures G83 X—Y—Z—R—O—F—K

Motion process:

- Drilling motion (-Z) → intermission feed
 Motion at the bottom of the hole →
- None


③ Retraction motion (+Z) → fast feed

G83 application example program:


M3 S2000 ;spindle rotation G90 G99 G83 X300 Y-250 Z-150 R-100 Q15 F120


;after orientation drill 1st hole, back to R point Y-550. ;after orientation drill 2nd hole, back to R point Y-750. ;after orientation drill 3rd hole, back to R point X1000. ;after orientation drill 4th hole, back to R point Y-550. ;after orientation drill 5th hole, back to R point G98 Y-750. ;after orientation drill 6th hole, back to start plane G80 ;cancel fixed cycle G28 G91 X0 Y0 Z0 ;back to reference point M5 ;spindle rotation stop M30

;after




SIEMENS














Cor Beg ISC Not	nmo jinnii) mo	n I ngi dei pa	SO is "O of 80 tible	08D: with the p		Common O0001; G0 X50 Y5 G04 X5 M3 S1000 	-	-	808D ISO program O0001: Delete this line G0 X50 Y50 Z50 M5 G04 X5 M3 S1000
Tool Type #2	T 1 2 3 4 8 10	1 1 1	H 0 0 0 0 0 0	Length	Active t Radius 5.000 6.000 5.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000		New tool Edges Delete tool Search	must ope first and f 2 commo ① Direct button on mode. (We rect od!) ② Enter and exec	standard DIN mode, you in the H list in the tool list ill in the data accordingly in methods use of the ISO switch the PPU to enter ISO commend the 1st meth- code G291 in MDA mode ute. When the "Reset" is the H list in the tool list is

Note: Every tool only can use the H value corresponding to the edge.

In the graphic above, T2 H1 cannot be executed.

Step 3 Program execution



Make sure the current system is in ISO mode! Make sure all preparations and safety measures have been performed!

Operate as described above.

Tool and workpiece setup \rightarrow simulation \rightarrow test \rightarrow machining.

Step 4 Transfer the ISO files in the 808D to the USB device.

Connect the USB device with sufficient memory to the USB interface on the PPU.

Press the "NC" SK on the PPU.



Сору

🖞 USB

Paste

Use the "Cursor + Select" keys to select the required program which is then highlighted.


Press the "Copy" SK on the PPU.

Press the "USB" SK on the PPU.

Press the "Paste" SK on the PPU.

A specified ISO program is then stored in the USB and can be executed as required.






Step 5 Sample program



Make sure the current system is in ISO mode! Make sure all preparations and safety measures have been performed!



ISO programs can be executed in the 808D as follows:

N10	G291
N20	T1M6
N30	G0G54G90G40
N40	M3S1200F200
N50	G43H1Z50
N60	G0X0Y-70
N70	Z5M8
N80	G1Z-5
N90	G01G41X20D1
N100	G03X0Y-50R20
N120	G1X-50,R10
N130	Y50,R10
N140	X50,R10
N150	Y-50,R10
N160	X40
N170	X0
N180	G03X-20Y-70R20
N190	G1G40X0
N200	G0Z50

Note: This program opens/exits


ISO mode with theG291/G290 command. It is recommended to use the first method to open ISO mode — using the ISO mode active button on the PPU (described above)

N210 T2M6 N220 M3S3000F100 N230 G43H2Z50 N240 G0X40Y-40 N250 Z20 N260 G81Z-2R10 N270 Y40 N290 X-40 N300 Y-40 N310 G80 N320 G0Z50 N330 T3M6 N340 M3S3000F100 N350 G43H3Z50 N360 G73Z-20R10Q5 N370 Y40 N380 Y-40 N390 X40 N400 Y40 N410 G80 N420 G0G40G90G49Z100 N430 M09 N440 G290

N450 M30

Operating and Programming — Milling





Standard Siemens programming. Machining the same workpiece as described above (can be compared with the ISO code).

N10 T1D1M6 ; contour milling tool N20 G54G90G40G17 N30 M3S2000M8 N40 G0Z25 N50 X0Y-70 N55 CYCLE72("CONT1:CONT1 E", 50, 0, 2, -5, 2.5, 0.1, 0.1, 200, 200, 111, 41, 2, 20, 200, 2, 20) N60 T2D1M6 ; guill, drill center hole N70 M3S2500M8 N80 MCALL CYCLE82(50, 0, 2, 0, 2, 0) N90 CYCLE802(111111111, 11111111, 40, -40, 40, 40, -40, 40, -40, -40, ,) N100 MCALL N110 T3D1M6 ; quill; deep hole drilling N120 M3S2500M8 N130 MCALL CYCLE83(50, 0, 2, -20, .-5, .3, 0.5, 1, 1, 1, 3, 3, 0, .0) N140 CYCLE802(111111111, 11111111, 40. -40. 40. 40. -40. 40. -40, -40, ,) N150 MCALL

N160 G0G40G90Z60 N170 M09M05 N180 M30 The next paragraph describes the codes of the contour. The system will generate them automatically and does not affect the program execution. CONT1: ;#7_DIgK contour definition begin -Don't change!;*GP*;*RO*;*HD* N190 G17 G90 DIAMOF;*GP* N200 G0 X0 Y-50 :*GP* N210 G1 X-50 RND=10 :*GP* N220 Y50 RND=10 :*GP* N230 X50 RND=10 ;*GP* N240 Y-50 RND=10 :*GP* N250 X0 :*GP* ;CON,0,0.0000,5,5,MST:0,0,AX:X,Y,I, J:*GP*:*RO*:*HD* :S.EX:0.EY:-50:*GP*:*RO*:*HD* :LL.EX:-50:*GP*:*RO*:*HD* ;R,RROUND:10;*GP*;*RO*;*HD* :LU.EY:50:*GP*:*RO*:*HD* :R.RROUND:10:*GP*:*RO*:*HD* ;LR,EX:50;*GP*;*RO*;*HD* ;R,RROUND:10;*GP*;*RO*;*HD* :LD.EY:-50:*GP*:*RO*:*HD* ;R,RROUND:10;*GP*;*RO*;*HD* ;LL,EX:0;*GP*;*RO*;*HD* ;#End contour definition end - Don't change!:*GP*:*RO*:*HD*

CONT1 E::****CONTOUR ENDS *****



Notes




Notes

														_
														++
														++
														++
														++
 	 		 	 		 	 _							





Unit Content



G Functions

Group 1:	Group 1: Modally valid motion commands						
Name	Meaning						
G00	Rapid traverse						
G01 *	Linear interpolation						
G02	Circular interpolation clockwise						
G03	Circular interpolation counter-clockwise						
CIP	Circular interpolation through intermediate point						
СТ	Circular interpolation; tangential transition						
G33	Thread cutting with constant lead						
G331	Thread interpolation						
G332	Thread interpolation - retraction						

Group 2:	Group 2: Non-modally valid motion, dwell						
Name	Meaning						
G04	Dwell time preset						
G63	Tapping without synchronization						
G74	Reference point approach with synchronization						
G75	Fixed point approach						
G147	SAR - Approach with a straight line						
G148	SAR - Retract with a straight line						
G247	SAR - Approach with a quadrant						
G248	SAR - Retract with a quadrant						
G347	SAR - Approach with a semicircle						
G348	SAR - Retract with a semicircle						



Group 3: P	Group 3: Programmable frame						
Name	Meaning						
TRANS	Translation						
ROT	Rotation						
SCALE	Programmable scaling factor						
MIRROR	Programmable mirroring						
ATRANS	Additive translation						
AROT	Additive programmable rotation						
ASCALE	Additive programmable scaling factor						
AMIRROR	Additive programmable mirroring						
G110	Pole specification relative to the last programmed setpoint position						
G111	Pole specification relative to origin of current workpiece coordinate system						
G112	Pole specification relative to the last valid POLE						

Group 6: I	Group 6: Plane selection							
Name	Meaning							
G17 *	X/Y plane							
G18	Z/X plane							
G19	Y/Z plane							

Group 7: Tool radius compensation								
Name	Meaning							
G40 *	Tool radius compensation OFF							
G41	Tool radius compensation left of contour							
G42	Tool radius compensation right of contour							

Group 8:	Group 8: Settable zero offset							
Name	Meaning							
G500 *	Settable work offset OFF							
G54	1st settable zero offset							
G55	2nd settable zero offset							
G56	3rd settable zero offset							
G57	4th settable zero offset							
G58	5th settable zero offset							
G59	6th settable zero offset							

Group 9: Frame suppression							
Name	Name Meaning						
G53	Non-modal skipping of the settable work offset						
G153	Non-modal skipping of the settable work offset including base frame						

Group 10: Exact stop — continuous – path mode						
Name	Meaning					
G60 *	Exact positioning					
G64	Continuous — path mode					

Group 1	l: Exact stop, non-modal								
Name Meaning									
G09 Non-modal exact stop									
Group 12	2: Exact stop window modally effective								
Group 12 Name	2: Exact stop window modally effective Meaning								



Group 13: Workpiece measuring inch/metric								
Name	Meaning							
G70	Inch dimension data input							
G71 *	Metric dimension data input							
G700	Inch dimension data input; also for feedrate F							
G710	Metric dimension data input; also for feedrate F							

Absolute/incremental dimension modally effective
Meaning
Absolute dimensions data input
Incremental dimension data input


Group 15: Feedrate / Spindle modally effective					
Name	Meaning				
G94	Feedrate mm/min				
G95	Feedrate F in mm/spindle revolutions				

Group 16:	Feedrate override modally effective
Name	Meaning
CFC *	Feedrate override with circle ON
CFC * Feedrate override with circle ON CFTCP Feedrate override OFF	

Group 18:	Behavior at corner when working with tool radius compensation
Name	Meaning
G450 *	Transition circle
G451	Point intersection

Group 44: Path segmentation with SAR modally effective						
Name	Meaning					
G340 *	Approach and retraction in space (SAR)					
G341	Approach and retraction in the plane (SAR)					

Group 47:	External NC languages modally effective
Name	Meaning
G290 *	Siemens mode
G291	External mode





Technical Support Contact

Technical Support

If you have any questions about this product or this manual, contact the hotline:

Fax +	+86 1064 719990
Fax	+86 1064 719991
E-mail	4008104288.cn@siemens.com

Useful Siemens Websites

SINUMERIK Internet address

Further product information can be found at the following web site:

http://www.siemens.com/sinumerik



Notes

Everything ever wanted to know about SINUMERIK 808D: www.automation.siemens.com/mcms/m2/en/automation-systems/cnc-sinumerik/sinumerik-controls/sinumerik-808/Pages/sinumerik-808.aspx

Everything about shopfloor manufacturing: www.siemens.com/cnc4you

Everything about the SINUMERIK Manufacturing Excellence portfolio of services: www.siemens.com/sinumerik/manufacturing-excellence

Information about CNC training: www.siemens.com/sinumerik/training

Siemens AG Industry Sector Motion Control Systems P.O.Box 3180 91050 ERLANGEN GERMANY Subject to change without prior notice Order No.: Dispostelle 06311 WÜ/35557 WERK.52.2.01 WS 11113.0 Printed in Germany © Siemens AG 2012 The information provided in this brochure contains merely general descriptions or characteristics of performance which in actual case of use do not always apply as described or which may change as a result of further development of the products. An obligation to provide the respective characteristics shall only exist if expressly agreed in the terms of contract.

All product designations may be trademarks or product names of Siemens AG or supplier companies whose use by third parties for their own purposes could violate the rights of the owners.